



TO WHOM IT MAY CONCERN

On the request of Mr. B. Biswal, Principal, DAV Public School, Midnapore for a Certificate regarding safety and stability of the school building I with Junior Engineer inspected the said School Building along with principal and site Engineer (Ex. Executive Engineer ,PWD) Mr. G.H. Malakar of DAV School Midnapore on dated-15.07.2022

On the basis of inspection this is to Certify that:-

- 1) The School Building situated at plot no-8, Daak Bunglow Road, Post+P.S.+Dist-Midnapore W.B.,Pin-721101,appears structurally fit.
 - 2) The whole School Campus is protected with compound wall with necessary gates.
 - 3) The stair and corridor of all school building are sufficient for Comfortable ingress and egress.
 - 4) It appears that the quality of Construction and Maintenance of the buildings are satisfactory.
- N.B: The legal aspect has not been examined by the undersigned.

D. Biswal
Principal
03/08/22
DAV Pubic School
Midnapore

G.H. Malakar
Site Engineer
03/08/22
DAV Public School
Midnapore
Site Engineer
DAV Public School, Midnapore

Saheed Mangal Pandey Sarani
Junior Engineer
03/08/22
Midnapur Construction Sub-Division
Junior Engineer (P.W.D.)
Midnapur Construction Sub-Division
Section No.-III

Mandal
03/08/2022
Assistant Engineer
Midnapur Construction Sub-Division,
Assistant Engineer,
Midnapur Construction Sub-Division,
Public Works Department

Principal
DAV PUBLIC SCHOOL
Dakbunglow Road,
P.O-Midnapore
Dist- Paschim Medinipur,
Pin-721101 W.B