

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.

Dated: 12/08/23 *

It is certified that an inspection team headed by DR. SUBRATA KANTI NANDI

(Name of Officers with designation) from Assistant Superintendent,
Midnapore medical college & Hospital.

(Name of Department/ Office) inspected the DAV PUBLIC SCHOOL, MIDNAPORE

(Name & Address of the school) on 12/08/23 (date of inspection) and found that the
DAV PUBLIC SCHOOL, MIDNAPORE (Name of school) has safe drinking water
facilities for the students and members of staff of the institution and is maintaining the hygienic
sanitation condition in the school building & the campus as per norms prescribed by the Central/
State/ U.T. Govt.

The above is valid for a period of 03 (THREE) years.

Signature with Seal:

Name

Designation

Name & Address of the Office / Department :

To

DAV PUBLIC SCHOOL, MIDNAPORE

D-B ROAD, MIDNAPORE, W.B. 721101

(Name & Address of the Institution)

Subrata Kanti Nandi
12/08/23
DR. SUBRATA KANTI NANDI
Assistant Superintendent
MIDNAPORE MEDICAL
COLLEGE & HOSPITAL
Assistant Superintendent
Midnapore Medical College & Hospital
Paschim Medinipur

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.



MIDNAPORE MUNICIPALITY

MIDNAPORE

Estd:-1865

DIST- PASCHIM MEDINIPUR, PIN-721101.

Phone: (03222)275384, email-midnapurmunicipality@gmail.com



Memo no: 7225/PHS

Dated: 07.10.21

TO WHOM IT MAY CONCERN

This is to certify that DAV Public School is running at B Daak Bungalow Road, Midnapore, Dist Paschim Medinipur in the state of West Bengal, Holding No. 399/1, 793/G-353, Rangamati, Ward no. 24, total student near about 1960 and total area 05 acres (appr) having 30 nos. of classroom (Principal + Office + Common Room) and 07 activity rooms, 5 nos. of lab is existing building (G Floor, 1st floor). The School Authority has completed the construction of building as well as boundary wall about 10' height and sanitary accommodation in ground floor and 1st floor as per Municipal sanctioned plan vide no. 536 dated 04/12/1997.

Details of sanitation and health environment condition of the school building as well as water supply, fire safety arrangement are mentioned below: - in view of the above this administration has no objection regarding sanitation of school / water supply and building safety.

1. Sanitary & Health Condition

- (a) No. of W.C in G. Floor 12 nos. (5 western & 7 Indian)
- (b) No. of W.C 1st Floor 10 no. (4 western & 6 Indian)
- (c) No. of Urinals in G. Floor 12 nos.
- (d) No. of Urinals in 1st Floor 10 nos. and Pre - Primary block, ND Grover block (U. Construction) a separate sheet enclosed.

Time to time uses disinfectant articles like phenol, CaOCl₂, and also sprays anti lava medicine around the school premises. All dally waste of school deposited in a cover bin.

2. Drainage

- (a) Pucca with covered drain.

3. Water supply

(a) 07 (seven) over tanks each 1000 liters capacity and 4 no Deep tubewell, 10,000 liters water lifted daily (supply water) supplied from provided 07 aqua guard for student use and time to time cleared by using caocl₂. Municipal authority requested to clean the over head tanks time to time and observe all measures about supplying of purified water to the students total number aqua guard - 7

4. Fire Safety

- (a) 5 nos. of equipments (G. Floor 01, 1st floor 01, office 01, Computer Lab - 1, Chemistry Lab -01.
- (b) Municipal authority requested to provide 3 extra fire extinguishers (5 kg. each).
- (c) Fire protection system through the pipe line enter building has arrange by the school authority (necessary paper enclose).

5. Plantation

- (a) plantation each year has done by the school approx above 1000 nos. plant all around the boundary wall and enter inside of the school is plantation.
- (b) One Aarbal garden is there in the School Campus.
- (c) One cycle stand, smart class and basket ball ground also this in good condition in view of the above this authority is no objection regarding public health point of views.

Sanitary Inspector
Midnapore Municipality.

Sanitary Inspector
Midnapore Municipality



Chairperson

Board of Administrator
Midnapore Municipality.

PRE-PRIMARY BLOCK

Total No. Of Rooms = 14.

1. Ground Floor :

- a) Staff Toilet (One Indian and One Commode)
- b) For Girls Students (Five Indian One Commode)

2. First Floor:

- a) Boys (Urinal – four , One Commode, One Indian)

3. 2nd Floor:

- a) Girls (Urinal – four, and one Commode)

Fire Extinguisher in Pre Primary Block = 05 (Ground Floor 03 , 1ST Floor - 01 , 2ND Floor - 01)

N.D. GROVER BLOCK (UNDER CONSTRUCTION)

Total No of Rooms = 7

1. Ground Floor:

- a) Boys (Urinal – Four, One Commode)

Total No of Aquaguards in all three Buildings = 7

MAIN BUILDING (Near Gate)

No of W.C. in Groun Floor = 12 (Western - 5 and Indian - 7)

No of W.C. in First Floor = 10 (Western - 4 and Indian - 6)


No of Urinals in Ground Floor = 12

No of Urinal in First Floor = 10

Fire Extinguisher = 05 (Ground Floor - 01, First Floor - 01, Office- 01, Computer Lab- 1 , Chemistry Lab - 01)


Covid -19:

- (1) School authority maintained covid rule as per Govt. guide line.
- (2) Mask use\$ every student and staffs also.


Sanitary Inspector 03/10/21
Midnapore Municipality.

Sanitary Inspector
Midnapore Municipality




Chairperson 7/10/21
Board of Administrator
Midnapore Municipality.